

Attachment A: Digital Images

Page 1 of 5

March 10th, 2008

BOE Building 23rd Floor East

Sacramento, CA



- 1) Image of ambient air sampling location at front entry of BOE Building (Subject Building) located at 450 N Street, Sacramento, California at time of assessment.



- 2) Image of Ambient air sampling location on balcony of 23 South at time of assessment.



- 3) Image within 23 Eastern containment system indicating location of air sampling devices and air handling equipment at time of assessment.



- 4) Additional image of air sampling and air handling equipment within 23 East containment area at time of assessment.



- 5) Image within 23rd Floor east containment area indicating location of air sampling equipment and extent of perimeter and interior wall removal.



- 6) Image of protected office furnishings located within interior office where air sampling was performed as part of this assessment.



- 7) Close-up image of mini coffee bar cabinet location indicating wallboard and cabinet removal prior to clearance assessment within 23 East containment area.



- 8) Air sampling within 23 East containment perimeter office space indicating extent of exterior and interior wallboard removal.



- 9) Additional image of air handling equipment location within 23 East perimeter office at doorway location.



- 10) Image of air sampling equipment within 23 East containment area.